APMA OFFICE JURISDICTIONAL DETERMINATION	
File Number: POA-1988-00892 Waterway: Ready Bullion Creek	
Applicant: Rich Kruse APMA #:	7201
Sources:	
⊠ USGS: <u>Fairbanks D-3 1:63360</u>	
NWI: USFWS National Wetlands Mapper 2007 Imagery (accessed 8 June 2020)	
Soil Map: NRCS Greater Fairbanks Area Soil Survey & Greater Nenana Area Soil Survey (accessed 8 June	
<u>2020)</u>	
Aerial photo: date: Google Earth 2017 Imagery (accessed 5 June 2020), DigitalGlobe 2020 Imagery (accessed 8	
$\frac{June 2020}{2}$	
Site Photos, source: <u>Site photos were not available at the time of application due to snowpack</u>	
☐ Information provided in the APMA	
Site visit: By whom and what date: N/A	
Agency contact: Who, date, contact number: <u>N/A</u> INTRODUCTION:	
Application for permit to mine in Alaska (APMA 720). Project is located at Latitude 64.8546 N, Longitude	
148.0369 W, USGS Quad Map Fairbanks D-3, in Ester, Alaska.	
VEGETATION:	
Aerial photography shows that the vegetation includes <i>Betula papyrifera</i> (paper birch) and <i>Populus tremuloides</i>	
(quaking aspen) in areas where trenching is proposed for exploratory purposes. Vegetation is sparse to absent	
in old mine tailings, which is the majority of the proposed project area where mining operations will occur. Plots	
of land designated for mining in the applicants 5 year mining plan have been historically mined and are	
disturbed.	
Hydrophytic vegetation present: 🗌 Yes 🖾 No 📄 Unknown	
SOILS:	
110- Dumps, mine Hydric Soil Rating- Unranked	
118-Fairbanks silt loam, 12-20 percent slopes –Nonhydric	
119-Fairbanks silt loam, 20-30 percent slopes- Nonhydric	
144-Minto Silt Loam, 7 tp 12 percent slopes- Nonhydric	
173-Steese Silt Loam, 20-30% percent slopes- Nonhydric	
Hydric soils present: 🗌 Yes 🖾 No 📋 Unknown	
HYDROLOGY:	
Trenching points for exploration occur in areas with no hydrological flow or within areas of hydric soil. Hydrology	
has been mapped by the NWI (National Wetlands Inventory) to include a freshwater emergent wetland	
(PEM1Cx) (2007 Imagery) that occurs in four of the five years proposed mining plan. Due to the nature of the	
area, the more recent aerial imagery (2020 imagery), and the lack of vegetation on site, the area most likely has	
not naturalized or been able to hold an active wetland status. Pooling water may be seen in aerial imagery but	
this is most likely due to current mining and not to naturalization.	
Wetland hydrology present: 🗌 Yes 🗌 No 🛛 Unknown	
WETLANDS CONCLUSION: (Adapt the wording of this section	Size of disturbance area:
to the situation)	Wetlands: 0 acres
Although the applicant has proposed to placer mine near	Uplands: 1.7 acres
Ready Bullion Creek, the area abutting the creek is	Stream length before diversion: N/A
considered uplands, due to the vegetation signature as well	Stream diversion length: N/A
as the lack of soil evidence to be classified as a wetland.	
The applicant has stated that there will be a 25ft buffer	
between the creek and placer mine operations as well as no	
in stream work or stream diversions. A large portion of the	
proposed mining will occur in old mine tailings that have	
been altered and degraded. Trenching points for exploration	
are all located in upland areas and therefore not	
jurisdictional.	
	6/8/2020
6/8/2020	
Lindsey McCord	
Lindsey McCord	

Lindsey McCord Regulatory Specialist

Fairbanks Field Office