


MACAULAY SALMON HATCHERY SALTWATER REARING SITE Sedimentation since original (1987-88) dredging to -24.0'


•						
	130.7 cu. yds.	113.2 cu. yds.				
•	220.9 cu. yds.	193.3 cu. yds.	168.7 cu. yds.	147.1 cu. yds.	133.9 cu. yds.	129.3 cu. yds.
>	190.4 cu. yds.	171.7 cu. yds.	152.8 cu. yds.	126.6 cu. yds.	115.6 cu. yds.	126.5 cu. yds.
	167.4 cu. yds.	152.1 cu. yds.	136.1 cu. yds.	111.5 cu. yds.	101.4 cu. yds.	113.9 cu. yds.
>	152.1 cu. yds.	134.5 cu. yds.	117.5 cu. yds.	100.3 cu. yds.	91.3 cu. yds.	91.5 cu. yds.
•	146.5 cu. yds.	116.9 cu. yds.	97.8 cu. yds.	89.6 cu. yds.	88.7 cu. yds.	94.9 cu. yds.
>	150.6 cu. yds.	99.2 cu. yds.	74.7 cu. yds.	77.0 cu. yds.	93.4 cu. yds.	123.9 cu. yds.

Total material (w/footprint depicted) to be removed to achieve -24' depth ≈ 5,000 cu. yds

Date Prepared:	Applicant's Name:						
May 14, 2015	Douglas Island Pink & Chum, Inc. (DIPAC)						
MACAULAY SALMON HATCHERY							
JUVENILE SALMON SALTWATER REARING SITE							
MAINTENANCE DREDGING							
SITE DEVELOPMENT DIAGRAM							
Sec.(s) 9 T., 41	S., R. <u>67</u> E., <u>CR</u> M						
SHEET 2 OF 5	Gastineau Channel, Juneau, Alaska						









2. Lat. 58.16.42.07710 Lon. 134.22.58.05145

GASTINEAU 3. Lat. 58.16.44.51327 Lon. 134.22.54.00381

CHANNEL



DISPOSAL SITE COORDINATES								
CORNER	NORTHING	EASTING	CORNER	NORTHING	EASTING			
1	2,354,598	2,548,208	3	2,355,230	2,547,994			
2	2.354,985	2,547,775	4	2,354,843	2,548,427			



Date Prepared:

May 14, 2015

Douglas Island Pink & Chum, Inc. (DIPAC)

MACAULAY SALMON HATCHERY

JUVENILE SALMON SALTWATER REARING SITE

MAINTENANCE DREDGING

SITE DEVELOPMENT DIAGRAM

Sec.(s) 9 T., 41 S., R. 67 E., CR M

SHEET 5 OF 5 Gastineau Channel, Juneau, Alaska