

# ALASKA BASELINE EROSION ASSESSMENT

# **Erosion Information Paper - Grayling, Alaska**

Current as of February 27, 2008

## **Community Information**

Grayling (GRAY-leeng), population 174, is in Interior Alaska on the west bank of the Yukon River, east of the Nulato Hills, and 18 miles north of Anvik. The community is incorporated as a 2nd class city in the unorganized borough.

#### **Description of Erosion Problem**

The community of Grayling does not experience erosion problems from the Yukon River or other sources. The Alaska Division of Community and Regional Affairs produced *Grayling Community Profile Maps* at a scale of 1 inch = 200 feet in 1984, 1999 and 2006. None of the maps indicate areas of erosion or any appreciable change along the river bank.

### **Potential Damages**

No potential erosion damages or erosion problems have been identified in the community.

#### **Photos and Diagrams**

No photos were provided by community or other sources. A diagram of the Grayling community is attached.

#### References

Alaska DCRA. 1984, 1999, 2006. Grayling Community Profile maps, online: <a href="http://www.commerce.state.ak.us/dca/profiles/profile-maps.htm">http://www.commerce.state.ak.us/dca/profiles/profile-maps.htm</a> State of Alaska, department of commerce, community and economic development, division of community and regional affairs. USACE. 2008. Alaska Community Erosion Survey, OMB approved number 07100001, expires September 30, 2009 administered to Charlotte West, Grayling city clerk on February 27 who also spoke with Shirley Clark, Grayling Mayor on February 26, 2008.

## **Additional Information**

This information paper, as well as those for other communities, can be accessed on the internet at <a href="https://www.alaskaerosion.com">www.alaskaerosion.com</a>. For more information please contact the Corps of Engineers, project manager at (907) 753-5694 or email <a href="https://www.alaskaerosion.POA@usace.army.mil">Alaska.Erosion.POA@usace.army.mil</a>





Alaska District Corps of Engineers Civil Works Branch





Alaska Baseline Erosion Grayling, Alaska