

Nome Seawall

Condition of Improvements
31 December 2017
Nome Seawall, Nome, Alaska
(CWIS No. 010422 & 012770)

Authorization (1) Rivers and Harbors Act, 16 June 1948 (Public Law 80-649) as adopted, authorizes construction of a rock mound seawall extending easterly from the east jetty along the water front for a distance of 3,350 feet. (2) Section 101 (a) (1), P.L. 106-53, Water Resource Development Act of 1999, 106th Congress, provides for navigation improvements at Nome; a seawall extension of about 400 feet was built to ensure the blocked entrance of the Snake River, the previous harbor entrance channel, did not erode during storms.

Table 1

Existing Project	Length ft.	Height ft.
Seawall Revetment	3350	

Progress of Work

1949	Work begins on the seawall.
1951	Construction of the seawall is completed in June.
2000	Locals were notified of several areas requiring armor stone (1 to 6 units) to repair the seawall.
2001	The Nome seawall is found to be structurally sound, but forty-eight (9) ton armor stones are required to cover exposed core material at various locations. Local interests have been notified.
2002	The Nome seawall is found in “fair” condition but continues to need repair.
2003	Inspection of the Nome seawall finds the project functioning properly but still in need of some repair.
2004	The Nome seawall is overtopped by a severe storm in October. The structure survived intact with minor damage. Local authorities have been notified of the needed repairs.
2005	The September inspection of the seawall finds conditions relatively unchanged since the 2004 post-storm inspection. Recommendation is made to perform the needed repairs.

Progress of Work

2006	The Corps' inspection of the seawall along Front Street found the project in good condition except for an occasional missing stone and a small area missing an estimated six stones. It was recommended that the stones in the one area of concern be replaced. The seawall is extended about 400 feet as part of the Nome Navigation Improvements project.
2009	The seawall at Nome was inspected and appears to be in good condition.
2011	An inspection after a November storm found the Nome Sea Wall appears to be in good condition.
2012	Project inspection reveals a steepened section of revetment near the Aurora Hotel. Gaps in the armor stone layer are noted.
2013	Project inspection reveals no significant change from previous year.
2014	Project inspection reveals no significant change from previous year.
2015	Project inspection reveals no significant change from previous year.
2016	Maintenance activities repair damages noted from previous inspections. Some gaps in armor stones are noted around culverts.
2017	Project inspection reveals no significant change from previous year.

Table 2 Cost to Date

Project	Description	Cost \$
Cost data is unavailable for this project.		

Table 3 Range of Tides in feet

Tide Station	Mean Range	Diurnal Range	Extreme Range
946 8756 Nome AK	1.03	1.52	7.12

Nome Seawall, Nome, Alaska



Nome Seawall, August 2016



Nome Seawall, August 2015