DRY LAND APPROVED JURISDICTIONAL DETERMINATION FORM $^{1}\,$ **U.S. Army Corps of Engineers**

This form should be completed by following the instructions provided in Section IV of the JD Form Instructional Guidebook.

SECTION I: BACKGROUND INFORMATION

A. RI	EPORT COMPLETION DATE FOR	APPROVED	JURISDICTIONAL	. DETERMINATION (JD): October 14, 202
-------	---------------------------	----------	----------------	---------------------	--------------------

B. DISTRICT OFFICE, FILE NAME, AND NUMBER: POA-2021-00457

\mathbf{C}	PROJECT LOCATION	AND BACKGROUND INFORMATION:
· •	I NOULC'I LOCATION	AND BACKGROUND INFORMATION.

	State	: Alaska: Choose an item County/parish/borough City: Tetlin Junction				
Center coordinates of site (lat/long in degree decimal format): Lat. 63.43930 °N, Long. 142.54333 °W						
		Universal Transverse Mercator: USGS Quad Maps: Tanacross B-3 & B-4; Section: 7,8,9,10 and 16, Township:				
19 N., Range 15 E.						
	Name of nearest waterbody: Dennison Creek					
	Name	e of watershed or Hydrologic Unit Code (HUC): 190705021606				
	V	Check if map/diagram of review area is available upon request.				
		Check if other sites (e.g., offsite mitigation sites, disposal sites, etc) are associated with this action and are recorded on a different JD form.				
D.	REV	TEW PERFORMED FOR SITE EVALUATION (CHECK ALL THAT APPLY):				
	V	Office (Desk) Determination. Date: October 6, 2021				
		Field Determination. Date(s): Click here to enter a date.				

SECTION II: SUMMARY OF FINDINGS

A. RHA SECTION 10 DETERMINATION OF JURISDICTION.

There are no "navigable waters of the U.S." within Rivers and Harbors Act (RHA) jurisdiction (as defined by 33 CFR part 329) in the review

B. CWA SECTION 404 DETERMINATION OF JURISDICTION.

There are no "waters of the U.S." within Clean Water Act (CWA) jurisdiction (as defined by 33 CFR part 328) in the review area.

<u>SE</u> A.

CCTION III: DATA SOURCES.					
	PORTING DATA. Data reviewed for JD (check all that apply - checked items shall be included in case file and, where checked and				
	ested, appropriately reference sources below):				
~	Maps, plans, plots or plat submitted by or on behalf of the applicant/consultant: As submitted in the application				
	Data sheets prepared/submitted by or on behalf of the applicant/consultant.				
	Office concurs with data sheets/delineation report.				
	Office does not concur with data sheets/delineation report.				
	Data sheets prepared by the Corps: Click here to enter text.				
~	U.S. Geological Survey Hydrologic Atlas: Tanacross B-3 & B-4				
	USGS NHD data.				
	USGS 8 and 12 digit HUC maps.				
~	U.S. Geological Survey map(s). Cite scale & quad name: Tanacross B-3 & B-4, Scale 1:25000				
~	USDA Natural Resources Conservation Service Soil Survey. There are no existing soil surveys for this area.				
1	National wetlands inventory map(s). Cite name: Tanacross B-3 & B-4				
~	State/Local wetland inventory map(s): State of Alaska Department of Natural Resources Forest Vegetation Tanacross B-3 & B-4				
	FEMA/FIRM maps: N/A				
	100-year Floodplain Elevation is: Click here to enter text. (National Geodectic Vertical Datum of 1929)				
~	Photographs: Aerial (Name & Date): Google Earth Imagery dated 4/15/2020				
	or 🔽 Other (Name & Date): 2021 MaxMar Aerial Imagery, dated 9/26/2020				
	Previous determination(s). File no. and date of response letter: Click here to enter text.				
	Applicable/supporting case law: Click here to enter text.				
	Applicable/supporting scientific literature: Click here to enter text.				
[7]	Other information (please specify):				

¹ This form is for use only in recording approved JDs involving dry land. It extracts the relevant elements of the longer approved JD form in use since 2007 for aquatic areas and adds no new fields.

B. REQUIRED ADDITIONAL COMMENTS TO SUPPORT JD. EXPLAIN RATIONALE FOR DETERMINATION THAT THE REVIEW AREA ONLY INCLUDES DRY LAND:): The review area consists entirely of dry land. There are wetlands near the location, but do not occur within the footprint of the future project. Additionally, the shapefile of the wetlands appears to be shifted south and east and do not match the photo-signature for wetlands. The area has been partially excavated and gravel filled, and there is no presence of surface waters or hydrology indicators or vegetation typical of wetland areas.

Laurel A Gale

Date: October 14, 2021