

Appendix B

Observation Points – Field Notes and Photographs

September 29-30, 2016

This page intentionally left blank.



Site 4: Waterbody, upstream north. Photo taken September 29, 2016



Site 4: Waterbody, upstream south. Photo taken September 29, 2016



Site 4: Waterbody, downstream. Photo taken September 29, 2016



Site 5: Vegetation. Photo taken September 29, 2016



Site 5: Vegetation. Photo taken September 29, 2016



Site 7: Vegetation. Photo taken September 29, 2016



Site 7: Vegetation. Photo taken September 29, 2016



Site 8: Vegetation. Photo taken September 29, 2016



Site 8: Vegetation. Photo taken September 29, 2016



Site 9: Culvert. Photo taken September 29, 2016



Site 9: Upstream. Photo taken September 29, 2016



Site 9: Vegetation. Photo taken September 29, 2016



Site 9: Culvert. Photo taken September 29, 2016



Site 10: Culvert. Photo taken September 29, 2016



Site 10: Vegetation. Photo taken September 29, 2016



Site 11: Soil. Photo taken September 29, 2016



Site 11: Vegetation. Photo taken September 29, 2016



Site 11: Vegetation. Photo taken September 29, 2016



Site 12: Vegetation. Photo taken September 29, 2016



Site 12: Vegetation. Photo taken September 29, 2016



Site 14: Soil. Photo taken September 29, 2016



Site 14: Vegetation. Photo taken September 29, 2016



Site 14: Vegetation. Photo taken September 29, 2016



Site 15: South culvert. Photo taken September 29, 2016



Site 15: North culvert. Photo taken September 29, 2016



Site 16: Culvert. Photo taken September 29, 2016



Site 16: Waterbody, upstream. Photo taken September 29, 2016



Site 17: Waterbody, upstream. Photo taken September 29, 2016



Site 17: Waterbody, downstream. Photo taken September 29, 2016



Site 18: Waterbody, upstream. Photo taken September 29, 2016



Site 18: Waterbody, downstream. Photo taken September 29, 2016



Site 20: Pond. Photo taken September 29, 2016



Site 20: Vegetation. Photo taken September 29, 2016



Site 21: Vegetation. Photo taken September 29, 2016



Site 21: Vegetation. Photo taken September 29, 2016



Site 22: Vegetation. Photo taken September 29, 2016



Site 22: Vegetation. Photo taken September 29, 2016



Site 23: Waterbody, upstream. Photo taken September 29, 2016



Site 23: Waterbody, downstream. Photo taken September 29, 2016



Site 24: Soil. Photo taken September 29, 2016



Site 24: Vegetation. Photo taken September 29, 2016



Site 24: Vegetation. Photo taken September 29, 2016



Site 25: Soil. Photo taken September 29, 2016



Site 25: Vegetation. Photo taken September 29, 2016



Site 25: Vegetation. Photo taken September 29, 2016



Site 26: Soil. Photo taken September 29, 2016



Site 26: Vegetation. Photo taken September 29, 2016



Site 26: Vegetation. Photo taken September 29, 2016



Site 27: Channel. Photo taken September 29, 2016



Site 27: Upstream. Photo taken September 29, 2016



Site 28: Soil. Photo taken September 29, 2016



Site 28: Vegetation. Photo taken September 29, 2016



Site 28: Vegetation. Photo taken September 29, 2016



Site 29: Vegetation. Photo taken September 29, 2016



Site 29: Vegetation. Photo taken September 29, 2016



Site 30: Culvert. Photo taken September 29, 2016



Site 30: Waterbody, upstream. Photo taken September 29, 2016



Site 32: Vegetation. Photo taken September 29, 2016



Site 32: Vegetation. Photo taken September 29, 2016



Site 33: Vegetation. Photo taken September 29, 2016



Site 33: Dry stream channel. Photo taken September 29, 2016



Site 34: Waterbody, upstream. Photo taken September 29, 2016



Site 34: Waterbody, downstream. Photo taken September 29, 2016



Site 35: Towards larger channel. Photo taken September 29, 2016



Site 35: Vegetation. Photo taken September 29, 2016



Site 37: Vegetation. Photo taken September 29, 2016



Site 37: Vegetation. Photo taken September 29, 2016



Site 39: Culvert. Photo taken September 29, 2016



Site 39: Downstream. Photo taken September 29, 2016



Site 40: North. Photo taken September 29, 2016



Site 40: East. Photo taken September 29, 2016



Site 40: South. Photo taken September 29, 2016



Site 40: West. Photo taken September 29, 2016



Site 41: Culvert. Photo taken September 29, 2016



Site 41: Downstream. Photo taken September 29, 2016



Site 42: Soil. Photo taken September 29, 2016




Site 42: Vegetation. Photo taken September 29, 2016



Site 42: Vegetation. Photo taken September 29, 2016



Site 43: Culvert. Photo taken September 29, 2016



Site 43: Waterbody, downstream. Photo taken September 29, 2016



Site 44: Waterbody. Photo taken September 29, 2016



Site 44: Vegetation. Photo taken September 29, 2016



Site 45: Vegetation. Photo taken September 29, 2016



Site 45: Vegetation. Photo taken September 29, 2016



Site 48: Soil. Photo taken September 30, 2016



Site 48: Vegetation. Photo taken September 30, 2016



Site 48: Vegetation. Photo taken September 30, 2016



Site 50: Soil. Photo taken September 30, 2016



Site 50: Vegetation. Photo taken September 30, 2016



Site 50: Vegetation. Photo taken September 30, 2016



Site 51: Vegetation. Photo taken September 30, 2016



Site 51: Vegetation. Photo taken September 30, 2016



Site 52: Vegetation. Photo taken September 30, 2016



Site 52: Vegetation. Photo taken September 30, 2016



Site 53: Soil. Photo taken September 30, 2016



Site 53: Vegetation. Photo taken September 30, 2016



Site 53: Vegetation. Photo taken September 30, 2016



Site 54: Vegetation. Photo taken September 30, 2016



Site 54: Vegetation. Photo taken September 30, 2016



Site 55: Vegetation. Photo taken September 30, 2016



Site 55: Vegetation. Photo taken September 30, 2016



Site 57: Vegetation. Photo taken September 30, 2016



Site 57: Vegetation. Photo taken September 30, 2016



Site 58: Vegetation. Photo taken September 30, 2016



Site 58: Vegetation. Photo taken September 30, 2016



Site 60: Vegetation. Photo taken September 30, 2016



Site 60: Vegetation. Photo taken September 30, 2016



Site 61: Vegetation. Photo taken September 30, 2016



Site 61: Vegetation. Photo taken September 30, 2016



Site 62: Soil. Photo taken September 30, 2016



Site 62: Soil. Photo taken September 30, 2016



Site 62: Vegetation. Photo taken September 30, 2016



Site 62: Vegetation. Photo taken September 30, 2016



Site 64: Soil. Photo taken September 30, 2016



Site 64: Vegetation. Photo taken September 30, 2016



Site 64: Vegetation. Photo taken September 30, 2016



Site 65: Vegetation. Photo taken September 30, 2016




Site 65: Vegetation. Photo taken September 30, 2016



Site 66: Vegetation. Photo taken September 30, 2016



Site 66: Vegetation. Photo taken September 30, 2016



Site 67: Vegetation. Photo taken September 30, 2016



Site 67: Vegetation. Photo taken September 30, 2016



Site 68: Vegetation. Photo taken September 30, 2016



Site 68: Vegetation. Photo taken September 30, 2016



Site 69: Vegetation. Photo taken September 30, 2016



Site 69: Vegetation. Photo taken September 30, 2016



Site 70: Waterbody. Photo taken September 30, 2016



Site 70: Waterbody. Photo taken September 30, 2016



Site 71: Vegetation. Photo taken September 30, 2016



Site 71: Vegetation. Photo taken September 30, 2016